

#### Style South

01202 874044

Consort House Princes Road

## Style South East

01992 524385

Unit 5, 284 High Road North Weald Bassett CM16.6EC

### Style Midlands

01530 831144

Unit 3, Phoenix Park Telford Way Coalville Leicestershire

### Style North

01204 845590

The Old Stables 142a Chorley New Road Bolton Lancashire BL1 4NX

### Style Scotland

01259 750600

Townhouse Business Centre 10 Bank Street Tillicoultry FK13 6DP



FIS Contractors Gold Award Winners 2004 2008 2009 2010 2011 2014 2015 2016 2017

# Good as new! 25 year old moveable walls continue to operate smoothly thanks to Style's service packages

www.style-servicing.co.uk

At a major exhibition centre, two Huppe (now DORMA Huppe) moveable walls were installed 25 years ago to enable the space to be divided and opened up quickly, catering for daily changes to the use of the room.

As with most products, moveable walls have a lifespan, yet this can be dramatically extended with routine service and timely repairs.

A bit like a car, if treated well and serviced on time, an operable wall will continue to give you trouble-free service far longer than one that has been left unattended since day one.

"This is a great example of where routine servicing and the swift resolution of problems will extend the life of a moveable wall," said Style's service and aftercare director, Sjors Kuijs.

"The original carriers are still fitted and remain in good working order. Two years ago we were called in as they had a problem with a track junction which Style replaced with a new one, without delay and at very low cost.

"It means the relatively small investment made in having Style's service and repair team on hand has given a significant return, by protecting its longevity.

"A wall that isn't attended to can develop problems over time, resulting in the need for a complete replacement and this is far more expensive.

"We would urge anyone with a moveable wall to opt for one of Style's aftercare support packages – otherwise, it's the equivalent of buying a car and never getting it serviced or repaired."

















